

Tuesday, 11/03/2008 11:50:37 AM Date Linda Lacelle User. **Process Sheet Drawing Name** : WEARPAD : CU-DAR001 Dart Helicopters Services Customer Job Number : 37812 : 12784 Estimate Number : D35649 Part Number P.O. Number : D3564 REV D S.O. No. : **Drawing Number** : 11/03/2008 This Issue : N/A Project Number : NC Prsht Rev. : D : SMALL /MED FAB **Drawing Revision** : 11 Type First Issue 16 Material : 37238 -Previous Run : 31/03/2008 Qty: 30_ Um: Each **Due Date** Written By Checked & Approved By : Est Rev:A New Issue 07-03-08 ec Comment As per Rev C 07-07-09 JLM Est Rev:B As per Rev D 07-09-09 JLM Verified By:EC Est Rev:C Additional Product Job Number: Description: Seq. #: Machine Or Operation: 304/316 .063 Sheet 1.0 M304S16GA 30.03 Comment: Qtv.: 1.1550 sf(s)/Unit Total: 34.6500 sf(s) M304S16GA Stainless steel sheet 0.063" thick Batch: 106860 WATER JET 2.0 Comment: FLOW WATER JET 08 03 12 1-Cut as per Dwg D3564 *****(D3564-1F)**** Dwg Revi D Prog Rev: D 2-Deburr if necessary 3.0 202



Comment: INSPEC PARTS AS THEY COME OFF MACHINE

4.0

QC8

SECOND CHECK

wenter

Comment: SECOND CHECK


NC BRAKE



Comment: NC BRAKE

Deburr if necessary


Form on Brake as per Dwg D3564 using Jigs DT4 and DT







Date: Tuesday, 11/03/2008 11:50:37 AM User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: WEARPAD Job Number: 37812 Part Number: D35649 Job Number: Seq. #: Machine Or Operation: Description: Form Joggle as per Dwg D3564 on brake using Jig DT 6.0 QC5 INSPECT WORK FO CURRENT STEP 05:03-17 Comment: INSPECT WORK TO CURRENT STEP Ensure joggle as per dwg D3429 7.0 LARGE FAB 1 LARGE FABRICATION RESOURCE 1 Comment: LARGE FABRICATION RESOURCE 1 Description Batch Qty M107051 2059B Hardcoat Weld hardcoat as per Dwg D3564 QC# 10 VISUAL WELDING INSPECTION Comment: VISUAL WELDING INSPECTION QC5 INSPECT WORK TO CURRENT STEP Comment: INSPEC TO CURRENT STEP POWDER COATING m 106442 Comment: POWDER COATING Powder Coat Grey Sandtex (Ref. 4.3.5.6) as per QSI 005 4.3 11.0 INSPECT POWDER COAT/CHEMICAL POWDER COAT/CHEMICAL CONVERSION 12.0 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 identify and Stock Location:



Date:

Tuesday, 11/03/2008 11:50:37 AM

User:

Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: WEARPAD

Job Number: 37812

Part Number: D35649

Job Number:



Comment: FINAL INSPECTION/W/O RELEASE

Seq. #:

Machine Or Operation:

Description:

13.0

QC21

FINAL INSPECTION/W/O RELEASE


08/04/03


Job Completion





Le 26.04.03














	Work Order: 37812
DART AEROSPACE LTD	
Transistion: 11 to 406 d	Part Number: D3564-9
Description: Wearpad Rev: D	Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

x First Article		Prototype			
	Actual		Meth		

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
00.188	+0 005-0.001	0.193			NorN	1
0.300	010 C-1+	0.305			VOVN	
0 300	H- 2010	0.305	V		VOVN	
3 227	010.0-1+1	3.220	V		VEIN	*
6.000	H-0010	5.997	1	-	YWN	
18.00	11-0030	1800	4		MI	
18 000	H-0.010	18.000	4		T. M	
11.50	1+1-0 030	11.50	1		MI	
900	+1-0030	9.00	1		M.T	
						, .
						<i>*</i>
			8			·
	=					4
			a 4			*
						•
-					-	
	<u> </u>		(ototype Appro	oval: \

Measured by:	WINT	Audited by:	6	Prototype Approval:	N	
Date:	05 05 10	Date:	SA BLIU	Date:		vt
	080131		ocosi q			

Rev	Date	Change	Revised by	Approved
aves.	20:0	The second secon	KJ/JLM	
2 2 3	<u> </u>	New Issue		14



